Link Engine Management PC Link Updates

Released 12th October 2020

<u>PCLink version 5.6.8.3666 | DLL version 3659 | G4+ Firmware Version 5.6.8.3668</u>

New Features

- Added Mini R56 CAN stream.

Changes

- Added Turbo RPM function to Thunder DI11–16
- Added saturation check to Mini evap temperature in CAN stream to allow higher temperatures.
- Added APS (Main), Ethanol Content, Antilag Status, Launch Status, Traction Status and Cruise Control Status to Aim Dash Stream.
- Made Overrun Fuel Cut use APS when the APS signal is received over CAN.
- Added more data to Generic Dash CAN stream.
- Removed Trigger Scope image save button.
- Improved VVT setting visibility in User Defined mode on Monsoon ECUs.

Fixes

- Fixed Cruise Control Light functionality.
- Fixed CLL 3D trim limits issue.
- Fixed CAN transmitting signed value issue.