



Note:

Reluctor sensors
MUST be connected
with correct polarity.

Figure C02.1 - Link Reluctor Trigger Wiring