



Note:
As tested on a Honda H22A engine

While every effort is taken to ensure correctness, no responsibility will be taken for the consequences of any inaccuracies or omissions in this drawing.



AUTHOR
**Honda 24Tooth
Distributor**

DATE
25/8/2009

VERSION
1.0

DRAWING ID
C28

AUTHOR
PW